

WPR24LA192

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft inverted with left wing damage (Courtesy of the owner)



Photograph 2 - Aircraft inverted at accident site (Courtesy of the owner)



Photograph 3 - View of skid marks leading to inverted aircraft (Courtesy of owner)