

WPR24LA197

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to right wing. (Courtesy of owner)



Photograph 2 - View of damage to rudder. (Courtesy of pilot)