

Kathryn Whitaker
Aviation Accident Investigator
Office of Aviation Safety- Western Pacific Region

Date: August 21, 2024

Subject: WPR24LA209

Contact: Flo Ghighina, Airport Inspector/Obstructions Evaluator, Idaho
Transportation Department/Division of Aeronautics

Mr. Ghighina indicated that he visited Chamberlain Guard Station (U79) on August 5, 2024. Mr. Ghighina indicated that the main runway surface area was outlined/bordered by 3 ft tall white cones, and that the center 20-25ft portion of Runway 7-25 was in overall good repair. Outside of the center and most used portion of the main landing area, he characterized the area to have "abundant grass growth" and some larger rodent holes, which he estimated to be 6 to 8 inches in size.

Mr. Ghighina provided the following photographs:



