



Photo 1 – View of damage to vertical stabilizer, rudder, and right wing lift strut. (Courtesy airport ops)