

WPR24LA240

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of substantial damage to the left wing lift strut and damage to the horizontal stabilizer (Courtesy of pilot)