

Eric M. Gutierrez  
Air Safety Investigator  
Western Pacific Region

**Date:** July 27, 2024

**Subject:** WPR24LA256, Memorandum for Record

**Contact:** Edoardo Serra, Pilot

The following is a synopsis of the information provided by Mr. Serra during an in person interview.

While coming into land on runway 18 at the Wittman Regional Airport, Oshkosh, WI, he allowed the airplane to get too slow. During the landing flare, the airplane stalled and landed hard collapsing the left main landing gear. The airplanes left wing and empennage impacted the runway surface. The airplane then veered off the runway onto the grass, coming to rest upright. None of the occupants were injured.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

