

WPR24LA267


INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of accident airplane with left wing and fuselage damage (Courtesy of the FAA)



**Photograph 2 - View of accident airplane adjacent a building with damage to both wings
(Courtesy of the FAA)**



Photograph 3 - View of IPC excerpt with turbocharger, inlet house, and t-band clamp exemplar photo overlays



Photograph 4 - Front view of JPI EDM-700



Photograph 5 -Data sticker view of JPI EDM-700