

WPR24LA268

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane during examination




Photograph 2 - View of damage to forward fuselage




Photograph 3 - View of stabilator trim screw assembly



Photograph 4 - View of stabilator trim screw assembly



Photograph 5 - View of airplane POH cover page



Photograph 6 - View of POH preflight check list