

WPR24LA275

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Forward quartering view of airplane at accident site (courtesy of Concord Airport Operations)




Photograph 2 - View of fuselage to ground contact (courtesy of Concord Airport Operations)



Photograph 3 - Lower fuselage (Courtesy of Concord Airport Operations)



Photograph 4 - View of manual release assembly, gear motor, and torque tube



Photograph 5 - Manual release assembly housing and damage to side structure inhibiting movement of torque tube