

WPR24LA306

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the damage to the left wing spar (Courtesy of operator)