

WPR24LA312

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left wing and tail damage (Courtesy of pilot)



Photograph 2 - View of right horizontal stabilizer damage (Courtesy of pilot)