


WPR24LA314


INVESTIGATION PHOTOGRAPHS




Photograph 1 - Airplane at accident site. (Courtesy of LEO)




Photograph 2 - Engine removal from crate.



Photograph 3 - Engine mounted on exam stand.



Photograph 4 - Cylinder number 4 fuel injection assembly tube.



Photograph 5 - Cylinder number 4 fuel injection assembly tube.