

WPR25FA145

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident site from above.



Photograph 2 - Front view of accident airplane.



Photograph 3 - View of downed airport perimeter fence post.



Photograph 4 - View of downed airport perimeter fence post with black transfer mark.



Photograph 5 - View of tree with damaged limbs along extended runway center line.



Photograph 6 - View of damaged limbs along extended runway center line.