

WPR25LA004

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N7869G at accident site (Courtesy of airport manager)



Photograph 2 - Substantial damage to the left-wing spar (Courtesy of airport manager)



Photograph 3 - Left- and right-wing fuel samples showing contamination (Courtesy of Recovery agent)