

WPR25LA006

**INVESTIGATION PHOTOGRAPH**



**Photograph 1 - View of damage to the helicopter's left main landing gear strut and lower fuselage (Courtesy of operator)**