

WPR25LA011

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Accident Airplane (Courtesy of Pilot)



Photograph 2 - Accident Airplane (Courtesy of FAA)



Photograph 3 - Damaged aileron hinge and boost tab control rod (Courtesy of FAA)