

WPR25LA015

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the glider from the front left. (Courtesy of airport operations.)



Photograph 2 - View of the glider from aft left. (Courtesy of airport operations.)



Photograph 3 - View of substantial damage to empennage. (Courtesy of airport operations.)