

WPR25LA026

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of substantial damage to the rudder (Courtesy of operator)