

WPR25LA030

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Wreckage on Scene (Courtesy of Pilot)




Photograph 2 - Damage to Airplane (Courtesy of Pilot)



Photograph 3 - Cockpit Damage (Courtesy of Pilot)



Photograph 4 - Engine Damage (Courtesy of NTSB)



Photograph 5 - Internal view of left and right engine case halves, highlighting fretting to forward section of each case half (Courtesy of NTSB)



Photograph 6 - Photos showing fretting to each cylinder hold down plate (Courtesy of NTSB)