

WPR25LA032

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to right wing. (Courtesy of operator.)



Photograph 2 - View of damage to right wing. (Courtesy of operator.)



Photograph 3 - Diagram of ramp area. (Courtesy of operator.)