

WPR25LA035

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right wing damage (Courtesy of Pilot)



Photograph 2 - View of left horizontal Stabilizer damage (Courtesy of Pilot)