

- The Special Airworthiness Information Bulletin (SAIB CE-09-35) Carburetor Icing Prevention chart indicated Serious Icing conditions during the initial climb temperature of 48°F and dew point of 32° F.

