

WPR25LA037

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of inverted airplane and substantial damage to the right wing lift strut, vertical stabilizer and rudder (Courtesy of FAA)



Photograph 2 - Forward to aft view of inverted airplane with substantial damage to right wing lift strut (Courtesy of FAA)



**Photograph 3 - View of inverted airplane with damage to vertical stabilizer and rudder
(Courtesy of FAA)**



Photograph 4 - Onsite view of the airplane's fuel selector in the Both position (Courtesy of FAA)