

WPR25LA056

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane from the left. (Courtesy of the FAA.)



Photograph 2 - View of substantial damage to vertical stabilizer. (Courtesy of the FAA.)



Photograph 3 - View of substantial damage to wing strut. (Courtesy of the FAA.)



Photograph 4 - View of accident site. (Courtesy of the pilot.)