

WPR25LA060

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Forward lower fuselage damage. (Courtesy of FAA)



Photograph 2 - Lower fuselage damage. (Courtesy of FAA)



Photograph 5 - Airplane at nose gear examination. (Courtesy of FAA)



Photograph 6 - Damage to gear strut. (Courtesy of FAA)



Photograph 7 - Damage to pillar. (Courtesy of FAA)