

WPR25LA069

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N519CV at the accident site. (Courtesy of the Operator)



Photograph 2 - Substantial damage to the right wing, vertical stabilizer, and rudder. (Courtesy of the operator)



Photograph 3 - Substantial damage to the fuselage, left wing, left horizontal stabilizer, and elevator. (Courtesy of the operator)