


WPR25LA070

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of inverted airplane with substantial damage to the right wing (Courtesy of Pilot)



Photograph 2 - View of the mixture control arm and the bellcrank rod end bearing, absent the connecting bolt, washers and castellated nut (Courtesy of Aircraft Recovery)