

WPR25LA080

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane wreckage layout following initial recovery



Photograph 2 - Forward engine case during initial layout



Photograph 3 - Left wing and fuselage during initial layout (Courtesy of Piper Aircraft Company)



Photograph 4 - View of left wing during initial layout (Courtesy of Federal Aviation Administration)



Photograph 5 - Right stabilator end cap after second retrieval



Photograph 6 - Inboard right wing section after followup retrieval



Photograph 7 - Midspan right wing after followup retrieval