

WPR25LA086

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N5268K, showing substantial damage to the left wing. Source airport operations.