

WPR25LA096

INVESTIGATION PHOTOGRAPHS



Photograph 1 - A view of the airplane after completion of the forced landing. (Courtesy of the pilot.)



**Photograph 2 - A view of the fractured propeller blade and damaged engine cowlings.
(Courtesy of the pilot.)**



Photograph 3 - A view of the fractured propeller blade. (Courtesy of the pilot.)



Photograph 4 - A view of the substantial damage to the engine mount. (Courtesy of the pilot.)



Photograph 5 - A view of the substantial damage to the fuselage. (Courtesy of the pilot.)