


WPR25LA105


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Propeller blade damage (Courtesy of ERAU)



Photograph 2 - Floor damage (Courtesy of ERAU)



Photograph 3 - Firewall damage (Courtesy of ERAU)