

WPR25LA115

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to keel and main rotor blade (Courtesy of LEO)



Photograph 2 - View of damage to the rudder (Courtesy of LEO)