

WPR25LA132

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to left wing (Courtesy of Airport Manager)



Photograph 2 - View of damage to the left wing and aileron (Courtesy of Airport Manager)