

WPR25LA139

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage (Courtesy of Operator)



Photograph 2 - Left Wing Damage (Courtesy of Operator)



Photograph 3 - Rudder Damage (Courtesy of Operator)