

WPR25LA140

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N6682S at the accident site. (Courtesy of the pilot)



Photograph 2 - Left wing damage. (Courtesy of the pilot)



Photograph 3 - Right wing and aileron damage. (Courtesy of the pilot)