

WPR25LA141

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to lower fuselage (Courtesy of pilot)



Photograph 2 - View of damage to wings (Courtesy of pilot)