

WPR25LA176

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to elevator and horizontal stabilizer. (Courtesy of pilot)



Photograph 2 - View of damage to left wing lift strut. (Courtesy of pilot)