

WPR25LA192

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left-wing damage (Courtesy of airport operations)



Photograph 2 - View of damaged taxiway sign (Courtesy of airport operations)