


WPR25LA193

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site (Courtesy of Pilot)



Photograph 2 - Damaged Firewall, Fuselage, and Steering Shaft (Courtesy of Pilot)



Photograph 3 - Fractured Steering Shaft (Courtesy of Pilot)