

WPR25LA199

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of substantial damage to the tailboom. (Courtesy of airport operations).



Photograph 2 - Deformation of the helicopter skids. (Courtesy of airport operations).



Photograph 3 - Scrapes on ramp surface from helicopter impact. (Courtesy of airport operations).