

WPR25LA231

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of damage to the left wing lift strut and rudder (Courtesy of Pilot)