

WPR25LA234

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to fuselage. (Courtesy of FAA)



**Photograph 2 - View of damage to fuselage.
(Courtesy of FAA)**



**Photograph 3 - Damaged runway end light circled.
(Courtesy of FAA)**



**Photograph 4 - Damaged runway end light.
(Courtesy of FAA)**



**Photograph 5 - View of airplane from the rear.
(Courtesy of LEO)**