

WPR25LA262

INVESTIGATION PHOTOGRAPH



Photo 1 - View of the helicopter's right side tailboom striking light pole (Courtesy of BVS Airport Operations)



Photo 2 - View of substantial damage to the tailboom and fuselage (Courtesy of Social Media)