

WPR25LA270

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Left horizontal stab and elevator damage. (Courtesy of the pilot.)



Photograph 2 -Left wing tip fairing and aileron damage. (Courtesy of the pilot)



Photograph 3 - Left wing tip fairing damage. (Courtesy of the FAA)



Photograph 4 - Left outboard wing upper surface damage. (Courtesy of the FAA)