

WPR26LA003

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right wing strut damage (Courtesy of Pilot)



Photograph 2 - Right wing strut damage (Courtesy of Pilot)