

WPR26LA009

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of engine mount damage (Courtesy of Airport Operations)