

WPR26LA017

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left-wing lift strut damage (Courtesy of Pilot)



Photograph 2 - View of vertical stabilizer damage (Courtesy of Pilot)