

Grant D. Mills
Air Safety Investigator
Western Pacific Region

Date: 10/14/2025

Subject: WPR26LA017, Memorandum for Record

Contact: [REDACTED], Pilot

The following is a synopsis of the information provided by Mr. [REDACTED] in a telephone conversation.

The pilot of the airplane reported that he departed runway 7L at Deer Valley Airport, Phoenix, Arizona, for a personal flight. During the landing roll of a touch and go, the airplane veered left. He corrected with right rudder and left aileron input. The airplane continued to turn left, weathervaning into the crosswind. He lost directional control, and the airplane ground looped to the left. Subsequently, the airplane turned 180° to the left and came to rest inverted on the runway.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.