

WPR26LA028

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right wing damage (Courtesy of pilot/owner)



Photograph 2 - Empennage damage (Courtesy of pilot/owner)



Photograph 3 - Fuselage damage (Courtesy of pilot/owner)



Photograph 4 - Tailwheel assembly post-accident (Courtesy of pilot/owner)



Photograph 5 - Tailwheel assembly post-accident (Courtesy of pilot/owner)



Photograph 6 - Tailwheel assembly internal, post-accident (Courtesy of pilot/owner)



Photograph 7 - Tailwheel assembly internal, post-accident (Courtesy of pilot/owner)



Photograph 8 - Tailwheel assembly internal, post-accident (Courtesy of pilot/owner)