

WPR26LA033

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Vertical Stabilizer damage (Courtesy of Richfield PD))



Photograph 2 - Fuselage damage (Courtesy of Richfield PD)